



FIG. 1




Case No.:CS23595RL
Inventor: Mark Pecen et al
Motorola Attorney:
Randy Vaas
Outside Patent Agent:
Philip Premysler
Tel.: (561) 361-8066
Total Figures 8

FIG. 2




Case No.: CS23595RL
Inventor: Mark Pecen et al
Motorola Attorney:
Randy Vaas
Outside Patent Agent:
Philip Premysler
Tel.: (561) 361-8066
Total Figures 8

FIG. 3




Case No.: CS23595RL
Inventor: Mark Pecen et al
Motorola Attorney:
Randy Vaas
Outside Patent Agent:
Philip Premysler
Tel.: (561) 361-8066
Total Figures 8

FIG. 4



Case No.: CS23595RL
Inventor: Mark Pecen et al
Motorola Attorney:
Randy Vaas
Outside Patent Agent:
Philip Premysler
Tel.: (561) 361-8066
Total Figures 8

FIG. 5



Case No.: CS23595RL
Inventor: Mark Pecen et al
Motorola Attorney:
Randy Vaas
Outside Patent Agent:
Philip Premysler
Tel.: (561) 361-8066
Total Figures 8

FIG. 6






FIG. 7



Case No.: CS23595RL
Inventor: Mark Pecen et al
Motorola Attorney:
Randy Vaas
Outside Patent Agent:
Philip Premysler
Tel.: (561) 361-8066
Total Figures 8

FIG. 8



Case No.: CS23595RL
Inventor: Mark Pecen et al
Motorola Attorney:
Randy Vaas
Outside Patent Agent:
Philip Premysler
Tel.: (561) 361-8066
Total Figures 8